

# **Appendix A. Test Photos**

Report No.: FR512311AL

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01





## 1 Photographs of Conducted Emissions Test Configuration



Report No.: FR512311AL

**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR512311AL



#### **REAR VIEW**

SPORTON INTERNATIONAL INC. Page No. : A3 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01






## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A7

Report Version

: Rev. 01


Report No.: FR512311AL




FCC Test Report

Report No.: FR512311AL

### For radiated emissions 30MHz~1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7
Report Version : Rev. 01




FCC Test Report

Report No.: FR512311AL

For radiated emissions above 1GHz



**FRONT VIEW** 




**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A6 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR512311AL



**EUT took a close** view



EUT took a close view

SPORTON INTERNATIONAL INC. Page No. : A7 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01