

Report No.: FG512311

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01






Report No.: FG512311

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



Page No.

Report Version

: A2 of A6 : Rev. 01

REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456





Report No. : FG512311



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 30MHz~1GHz



Report No. : FG512311

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




Radio Test Report

Report No.: FG512311


: A5 of A6

: Rev. 01

For radiated emissions above 1GHz



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version



Radio Test Report

EUT take a close-up



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6

Report Version

: Rev. 01

Report No. : FG512311