Test report No.: 10569798S

APPENDIX 3: Photographs of test setup

Conducted emission






UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


Test report No.: 10569798S

Radiated emission



Rear Below 1GHz

above 1GHz



UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No.: 10569798S

Pre-check of the worst position

Transmitter



Antenna



Y-axis

RF Power 17
B-Cast cott 10H
Refersh time10.5SEC





END OF REPORT

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401