FCC Test Report Report No.: FR342319

# **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : 1 of 6


TEL: 886-3-327-3456 Report Version : Rev. 01



# 1 Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. : 2 of 6
TEL: 886-3-327-3456 : Report Version : Rev. 01





**SIDE VIEW** 


SPORTON INTERNATIONAL INC. : 3 of 6

TEL: 886-3-327-3456 : Rey. 01



# 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 




**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : 4 of 6
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report Report No.: FR342319

#### For radiated emissions 30MHz~1GHz



**FRONT VIEW** 



: 5 of 6


: Rev. 01

**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version



### For radiated emissions above 1GHz



## FRONT VIEW



Page No.

Report Version

: 6 of 6

: Rev. 01

### **REAR VIEW**

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456