

Report No.: FR611330B

Appendix E. Setup Photographs

<Conducted Emission>



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : E1 of E3 Report Issued Date: May 11, 2016 Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : E2 of E3
Report Issued Date : May 11, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR611330B



<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : E3 of E3
Report Issued Date : May 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR611330B