Test report No. : 10168692H-R1 Page : 24 of 26

FCC ID : 2ABSP-HEXA FEEDER

Issued date : March 3, 2014 Revised date : March 20, 2014

APPENDIX 3: Photographs of test setup

Conducted emission




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10168692H-R1 Page : 25 of 26

FCC ID : 2ABSP-HEXA FEEDER

Issued date : March 3, 2014 Revised date : March 20, 2014

Radiated emission



Photo 1



Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10168692H-R1 Page : 26 of 26

FCC ID : 2ABSP-HEXA FEEDER

Issued date : March 3, 2014 Revised date : March 20, 2014

Worst Case Position

with tag(1slot)



with tag(3slots)



without tag



End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124