Test report No. : 10093118H-A-R1
Page : 30 of 32
Issued date : March 3, 2014
Revised date : March 19, 2014
FCC ID : 2ABXRBVMCN5102

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1



Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10093118H-A-R1
Page : 31 of 32
Issued date : March 3, 2014
Revised date : March 19, 2014
FCC ID : 2ABXRBVMCN5102

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10093118H-A-R1
Page : 32 of 32
Issued date : March 3, 2014
Revised date : March 19, 2014
FCC ID : 2ABXRBVMCN5102

Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124