




**Appendix A. Test Photos** 

1. Photographs of Conducted Emissions Test Configuration



Report No.: FR611103AC

**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973





Report No.: FR611103AC



**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973



## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A3 of A5

Report Version

: Rev. 02


Report No.: FR611103AC






Report No.: FR611103AC

For radiated emissions 30MHz~1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5

Report Version


: Rev. 02






Report No.: FR611103AC

For radiated emissions above 1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5

Report Version :

: Rev. 02