





## LTE Band 4 / 1.4MHz

## Highest Channel / QPSK



## Highest Channel / 16QAM





## LTE Band 4 / 3MHz

## Lowest Channel / QPSK

## Lowest Channel / 16QAM











## LTE Band 4 / 5MHz

## Highest Channel / QPSK

## Highest Channel / 16QAM





Date: 23.APR.2016 14:26:38

Date: 23.APR.2016 14:27:33

## LTE Band 4 / 10MHz


## Lowest Channel / QPSK


## Lowest Channel / 16QAM





Date: 23.APR.2016 14:33:42


Date: 23.APR.2016 14:34:37















## LTE Band 5 / 1.4MHz

## Highest Channel / QPSK



## Highest Channel / 16QAM



## LTE Band 5 / 3MHz

## Lowest Channel / QPSK

## Lowest Channel / 16QAM



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL : 86-0512-5790-0158

FAX : 86-0512-5790-0958


FCC ID : 2ACCJA018


Page Number : A158 of A183

Report Issued Date : Aug. 09, 2016

Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5









## LTE Band 5 / 5MHz

## Highest Channel / QPSK

## Highest Channel / 16QAM



## LTE Band 5 / 10MHz

## Lowest Channel / QPSK

## Lowest Channel / 16QAM

