

Report No. : FR5D1401D

Appendix D. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : D1 of D2
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0



Report No. : FR5D1401D

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : D2 of D2
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0