

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D1 of D3
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.2


Report No.: FR642504C

<Radiated Emission>


802.11b/n HT20/HT40

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D3
Report Issued Date : May 27, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2

Report No.: FR642504C




FCC RF Test Report


802.11g

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D3 of D3
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report No.: FR642504C

Report Template No.: BU5-FR15CWL Version 1.2