

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : B1 of B3
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.1


Report No.: FR611504B




<Radiated Emission>

Z Plane for Bluetooth v4.0 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : B2 of B3
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.1


Report No.: FR611504B




<Radiated Emission>

X Plane for Bluetooth v4.2 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : B3 of B3
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.1

Report No.: FR611504B