

# Appendix D. Setup Photographs

### <Conducted Emission for Model 6055U>

#### Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D1 of D4
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report No.: FR670106C

Report Template No.: BU5-FR15CWL Version 1.2



### <Conducted Emission for Model 6055A>

#### Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D4
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2

Report No.: FR670106C




# <Radiated Emission>


802.11b/n HT20/HT40

**Z** Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D3 of D4
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2

Report No.: FR670106C




# FCC RF Test Report


802.11g

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018

Page Number : D4 of D4 Report Issued Date: Aug. 09, 2016 Report Version : Rev. 01

Report No.: FR670106C

Report Template No.: BU5-FR15CWL Version 1.2