

Appendix A. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : A1 of A3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01


Report No.: FR511301-30D




Report No.: FR511301-30D

<Radiated Emission>

Y Plane



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : A2 of A3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01



Report No. : FR511301-30D

<Radiated Emission for Spot Check

Y Plane



From 9kHz~30MHz



From 30MHz~1GHz

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : A3 of A3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01