

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C1 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.2


FCC RF Test Report

<Radiated Emission>


802.11b/n HT20

X Plane

LF



 ${\sf HF}$



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C2 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2




FCC RF Test Report


802.11g

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C3 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2




FCC RF Test Report


802.11n HT40

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C4 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2