

Appendix D. Setup Photographs

<Conducted Emission> Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D1 of D4
Report Issued Date : May 27, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWLB4 AC Version 1.2


Report No.: FR642504F




<Radiated Emission>

Z Plane For WLAN 5GHz 802.11n HT40/802.11ac VHT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D4
Report Issued Date : May 27, 2016
Report Version : Rev. 01


Report No.: FR642504F

Report Template No.: BU5-FR15EWLB4 AC Version 1.2




Y Plane For WLAN 5GHz 802.11ac VHT80

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D3 of D4
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report No.: FR642504F

Report Template No.: BU5-FR15EWLB4 AC Version 1.2






Z Plane For WLAN 5GHz 802.11a/802.11n HT20/802.11ac VHT40 LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D4 of D4
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report No.: FR642504F

Report Template No.: BU5-FR15EWLB4 AC Version 1.2