

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : D1 of D4
Report Issued Date : May 26, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2







<Radiated Emission>

Z Plane for WLAN 802.11b/n HT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : D2 of D4
Report Issued Date : May 26, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2






X Plane for WLAN 802.11g

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : D3 of D4
Report Issued Date : May 26, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2






Z Plane for WLAN 802.11n HT40

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : D4 of D4
Report Issued Date : May 26, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2