

Report No.: FR670106D

## **Appendix D. Setup Photographs**

## <Conducted Emission for Model 6055U>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D1 of D3
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.0



Report No.: FR670106D






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D3
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.0



## Report No.: FR670106D

## <Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D3 of D3
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0