

Report No. : FR611504-04D

Appendix D. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : D1 of D2
Report Issued Date : May 26, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0



<Radiated Emission>



Report No.: FR611504-04D

From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : D2 of D2
Report Issued Date : May 26, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0