

# Appendix D. Setup Photographs

## <Conducted Emission>

#### Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D1 of D3
Report Issued Date : May 27, 2016
Report Version : Rev. 01


Report No.: FR642504B

Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.3


### <Radiated Emission>

#### Y Plane for Bluetooth v4.0 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D3
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report No.: FR642504B


Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.3

#### Z Plane for Bluetooth v4.2 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D3 of D3
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.3

Report No.: FR642504B