

Appendix D. Setup Photographs

<Conducted Emission> Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Report Issued Date: May 27, 2016
Report Version: Rev. 01
Report Template No.: BU5-FR15EWL AC Version 1.4

Page Number

: D1 of D4


Report No.: FR642504E




<Radiated Emission>

Z Plane For WLAN 5GHz 802.11n HT40/802.11ac VHT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D4
Report Issued Date : May 27, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC Version 1.4

Report No.: FR642504E




Y Plane For WLAN 5GHz 802.11ac VHT80

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D3 of D4
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report No.: FR642504E

Report Template No.: BU5-FR15EWL AC Version 1.4






Z Plane For WLAN 5GHz 802.11a/802.11n HT20/802.11ac VHT40 LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D4 of D4
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report No.: FR642504E

Report Template No.: BU5-FR15EWL AC Version 1.4