

## Appendix C. Setup Photographs

## <Conducted Emission> Mode 2



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C1 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01

Report No.: FR611504F


Report Template No.: BU5-FR15EWLB4 AC Version 1.2




## <Radiated Emission>

## Y Plane For WLAN 5GHz 802.11a

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C2 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01


Report No.: FR611504F

Report Template No.: BU5-FR15EWLB4 AC Version 1.2




Z Plane For WLAN 5GHz 802.11n HT20/HT40

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C3 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01

Report No.: FR611504F


Report Template No.: BU5-FR15EWLB4 AC Version 1.2



Z Plane For WLAN 5GHz 802.11ac VHT20/VHT40/VHT80 LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C4 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC Version 1.2

Report No.: FR611504F