

### Report No.: FR611504D

# Appendix D. Setup Photographs

#### <Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015

Page Number : D1 of D2 Report Issued Date : Apr. 22, 2016 Report Version : Rev. 01 Report Template No.: BU5-FR15CNFC Version 1.0




## Report No.: FR611504D

#### <Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015

Page Number : D2 of D2 Report Issued Date : Apr. 22, 2016 Report Version : Rev. 01 Report Template No.: BU5-FR15CNFC Version 1.0