

est Report No. : FR561105E

# **Appendix C. Setup Photographs**

## <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACDKBP2B001AM1 Page Number : C1 of C4
Report Issued Date : Aug. 24, 2015
Report Version : Rev. 01




Report No. : FR561105E

### <Radiated Emission>

Y Plane for WLAN 5GHz 802.11a/802.11ac VHT40

LF



HF




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACDKBP2B001AM1 Page Number : C2 of C4
Report Issued Date : Aug. 24, 2015
Report Version : Rev. 01




### X Plane for WLAN 5GHz 802.11n HT20/HT40

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACDKBP2B001AM1 Page Number : C3 of C4
Report Issued Date : Aug. 24, 2015
Report Version : Rev. 01

Report No.: FR561105E



### Z Plane for WLAN 5GHz 802.11ac VHT20/VHT80

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACDKBP2B001AM1 Page Number : C4 of C4
Report Issued Date : Aug. 24, 2015
Report Version : Rev. 01

Report No.: FR561105E