

Report No. : FR4D2338-01

# **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





# 1 Photographs of Conducted Emissions Test Configuration

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A6

Report Version

: Rev. 01

Report No. : FR4D2338-01





Report No. : FR4D2338-01



**SIDE VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01






### 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**Report No. : FR4D2338-01** 

**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



### FCC Test Report

#### For radiated emissions 30MHz~1GHz

#### Mode 2



Report No. : FR4D2338-01

: A5 of A6

: Rev. 01

#### **FRONT VIEW**



#### **REAR VIEW**

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version




## FCC Test Report


Report No. : FR4D2338-01

For radiated emissions above 1GHz

Mode 2



#### **FRONT VIEW**



Page No.

Report Version

: A6 of A6

: Rev. 01

**REAR VIEW** 

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456