


Appendix A. Test Photos

Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A5

Report Version

: Rev. 01

Report No.: FR4D0476





Report No. : FR4D0476



Radiated below 1GHz Test




SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A5

Report Version : Rev. 01



FCC Test Report



SPORTON INTERNATIONAL INC. Pag
TEL: 886-3-3273456 Rep


FAX: 886-3-3270973

Page No. : A3 of A5
Report Version : Rev. 01


Report No.: FR4D0476



CC Test Report Report No.: FR4D0476



Radiated above 1GHz Test



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A4 of A5

Report Version

: Rev. 01



FCC Test Report Report No.: FR4D0476



SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-3273456 Report Version

: A5 of A5

: Rev. 01

FAX: 886-3-3270973