Test report No.
 : 12531961H-A

 Page
 : 37 of 39

 Issued date
 : October 29, 2018

 FCC ID
 : 2ACJJPC1420001

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 12531961H-A

 Page
 : 38 of 39

 Issued date
 : October 29, 2018

 FCC ID
 : 2ACJJPC1420001

Radiated Spurious Emission



Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 12531961H-A

 Page
 : 39 of 39


 Issued date
 : October 29, 2018

 FCC ID
 : 2ACJJPC1420001


Worst Case Position

Below 1 GHz (Horizontal: X-axis/ Vertical: X-axis) Above 1 GHz (Horizontal: X-axis/ Vertical: Y-axis)


X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124