
**Appendix A. Test Photos** 

Report No.: FR422023-02

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01



# 1 Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01






**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01




## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 




**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01



### For radiated emissions 30MHz~1GHz



#### **FRONT VIEW**




#### **REAR VIEW**

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7
Report Version : Rev. 01



For radiated emissions above 1GHz



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A6 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01



#### **EUT took a close view**



#### **FRONT VIEW**



#### **REAR VIEW**

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A7 of A7

Report Version : Rev. 01