

Report No. : FR470298

# **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973



FCC Test Report No.: FR470298

## 1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report No. : FR470298

For radiated emissions 30MHz~1GHz



**FRONT VIEW** 



REAR VIEW


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A5
Report Version : Rev. 01




FCC Test Report No. : FR470298

#### For radiated emissions above 1GHz



#### **FRONT VIEW**



### **REAR VIEW**

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456


FAX: 886-3-327-0973

Page No. : A4 of A5

Report Version : Rev. 01







Report No. : FR470298

EUT take a close-up

SPORTON INTERNATIONAL INC. Page No. : A5 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973