
3. Internal Photograph of EUT


Brand Name: Tramigo; Model Name: T23 Fleet

Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 10 of 28 Report Issued Date : Jul. 30, 2014

Report No.: EP470201





TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 11 of 28 Report Issued Date : Jul. 30, 2014

Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 12 of 28
Report Issued Date : Jul. 30, 2014






TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 13 of 28
Report Issued Date : Jul. 30, 2014
Report Version : Rev. 01



Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304

: 14 of 28 Page Number Report Issued Date: Jul. 30, 2014 Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 15 of 28
Report Issued Date : Jul. 30, 2014




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 16 of 28
Report Issued Date : Jul. 30, 2014
Report Version : Rev. 01



Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304

Page Number : 17 of 28 Report Issued Date: Jul. 30, 2014

: Rev. 01 Report Version



Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304

Page Number : 18 of 28 Report Issued Date: Jul. 30, 2014



Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304

Page Number : 19 of 28 Report Issued Date: Jul. 30, 2014 : Rev. 01 Report Version




Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304


Page Number : 20 of 28 Report Issued Date: Jul. 30, 2014 : Rev. 01 Report Version

Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 21 of 28
Report Issued Date : Jul. 30, 2014

Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 22 of 28
Report Issued Date : Jul. 30, 2014
Report Version : Rev. 01

Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 23 of 28
Report Issued Date : Jul. 30, 2014
Report Version : Rev. 01

Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 24 of 28
Report Issued Date : Jul. 30, 2014

Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 25 of 28
Report Issued Date : Jul. 30, 2014
Report Version : Rev. 01

Report No.: EP470201




TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 26 of 28
Report Issued Date : Jul. 30, 2014
Report Version : Rev. 01

Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 27 of 28
Report Issued Date : Jul. 30, 2014
Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304

Page Number : 28 of 28 Report Issued Date: Jul. 30, 2014 Report Version : Rev. 01