Test report No. : 10392826H-A-R1
Page : 26 of 27
Issued date : August 27, 2014
Revised date : September 5, 2014
FCC ID : 2ACS48600043

## **APPENDIX 3: Photographs of test setup**

## **Radiated Spurious Emission**



Photo 1




Photo 2


## UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10392826H-A-R1
Page : 27 of 27
Issued date : August 27, 2014
Revised date : September 5, 2014
FCC ID : 2ACS48600043

Worst Case Position (Horizontal: Z-axis/ Vertical: Y-axis)







**End of Report** 

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124