Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A9
TEL: 886-3-327-3456 Report Version : Rev. 01



1 Photographs of Conducted Emissions Test Configuration

Mode 2



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A9
TEL: 886-3-327-3456 Report Version : Rev. 01





SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A9
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report Report No.: FR5N1918

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A4 of A9 : Rev. 01

Report Version





SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A9 TEL: 886-3-327-3456 Report Version : Rev. 01



2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456


FAX: 886-3-327-0973

Page No. : A6 of A9 Report Version : Rev. 01




For radiated emissions 30MHz~1GHz

Mode 1



FRONT VIEW



: A7 of A9


: Rev. 01

REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version



Mode 2



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A8 of A9 Report Version : Rev. 01



For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A9 of A9

Report Version

: Rev. 01