Test report No. : 10618697H-A-R1
Page : 16 of 18
Issued date : May 15, 2015
Revised date : June 8, 2015
FCC ID : 2AD4RTRC-SS310

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


: 10618697H-A-R1 Test report No. Page : 17 of 18 **Issued date** : May 15, 2015 Revised date : June 8, 2015 FCC ID : 2AD4RTRC-SS310

Worst Case Position

CONTROLLER, ID KEY

Below 30MHz: X-axis Above 30MHz (Horizontal: Y-axis / **Vertical: Y-axis)**





Z-axis


ID Receiving antenna

Below 30MHz: X-axis Above 30MHz (Horizontal: X-axis / **Vertical: X-axis)**





Y-axis



Z-axis

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10618697H-A-R1
Page : 18 of 18
Issued date : May 15, 2015
Revised date : June 8, 2015
FCC ID : 2AD4RTRC-SS310

Worst Case Position







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124