Test report No. : 10211033H-A-R1

Page : 36 of 37

Issued date : September 30, 2014
Revised date : November 7, 2014
FCC ID : 2ADBK93JP2KS8580000

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10211033H-A-R1

Page : 37 of 37

Issued date : September 30, 2014
Revised date : November 7, 2014
FCC ID : 2ADBK93JP2KS8580000

Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)


X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124