## Telecell Mobile (H.K) Ltd.

RM 801 Metro Ctr II, 21 Lam Hing Street, Kln Bay, Hong Kong Tel: +852 27599962 Fax: +852 27599711 Email: regina@telecellmobile.com

## **Attestation Letter**

2016/11/18

To: FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Dear Sir or Madam,

The RF chip, model MT6753, installed in product Mobile Phone with FCC ID: 2ADX3X55L. For use in USA this chip will not support/enable the LTE band40, band41 function. The LTE band40, band41 function has been shielded by the manufacturer using the software.

Sincerely Yours,

Signature:

Regina Wong

Product Manager