Test report No.
 : 10814099H-A-R1

 Page
 : 32 of 34

 Issued date
 : July 21, 2015

 Revised date
 : July 27, 2015

 FCC ID
 : 2AE35M1REV3

## **APPENDIX 3: Photographs of test setup**

## **Conducted Emission**



Photo 1




Photo 2

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 10814099H-A-R1
Page : 33 of 34
Issued date : July 21, 2015
Revised date : July 27, 2015
FCC ID : 2AE35M1REV3

#### **Radiated Spurious Emission**



Photo 1





Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 10814099H-A-R1
Page : 34 of 34
Issued date : July 21, 2015
Revised date : July 27, 2015
FCC ID : 2AE35M1REV3

### Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)







**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124