




Report No.: EP532744-01







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B4 of B23 Report Version : Rev. 01












Page Number : B5 of B23
Report Version : Rev. 01










Page Number : B6 of B23
Report Version : Rev. 01











Page Number : B7 of B23
Report Version : Rev. 01


















Page Number : B9 of B23 Report Version : Rev. 01












SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B10 of B23 Report Version : Rev. 01











Page Number : B11 of B23 Report Version : Rev. 01




















Page Number : B13 of B23 Report Version : Rev. 01












Page Number : B14 of B23 Report Version : Rev. 01











Page Number : B15 of B23 Report Version : Rev. 01









Page Number : B16 of B23 Report Version : Rev. 01










Page Number : B17 of B23 Report Version : Rev. 01









Page Number : B18 of B23
Report Version : Rev. 01










Page Number : B19 of B23 Report Version : Rev. 01



Report No. : EP532744-01



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B20 of B23 Report Version : Rev. 01