

Report No. : FR632203-01D

Setup Photographs

<Conducted Emission>



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 1 of 3
Report Issued Date : Jun. 10, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC MA Version 1.4



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 2 of 3
Report Issued Date : Jun. 10, 2016
Report Version : Rev. 01

Report No.: FR632203-01D

Report Template No.: BU5-FR15EWL AC MA Version 1.4



Report No.: FR632203-01D


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 3 of 3
Report Issued Date : Jun. 10, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC MA Version 1.4