

## Report No.: FR632203-01C

# **Setup Photographs**

# <Conducted Emission>



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 1 of 4
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 1.3







Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 2 of 4
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL MA Version 1.3



# <Radiated Emission>

#### Y Plane for SISO Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 3 of 4
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01

Report No.: FR632203-01C


Report Template No.: BU5-FR15CWL MA Version 1.3



#### <Radiated Emission>

### X Plane for MIMO Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 4 of 4
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01

Report No.: FR632203-01C

Report Template No.: BU5-FR15CWL MA Version 1.3