

Report No. : FR482217-02

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





Mode 1



Report No. : FR482217-02

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A6

Report Version

: Rev. 01



Report No. : FR482217-02



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973






2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No. : FR482217-02

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6 Report Version : Rev. 01




FCC Test Report


Report No. : FR482217-02

For radiated emissions 30MHz~1GHz

Mode 2



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6 Report Version : Rev. 01



FCC Test Report


Report No. : FR482217-02

: A6 of A6


: Rev. 01

For radiated emissions above 1GHz

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version

FAX: 886-3-327-0973