Test report No. : 11023664H-A
Page : 31 of 32
Issued date : June 16, 2016
FCC ID : 2AEFK-DL8791

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11023664H-A Page : 32 of 32 **Issued date** : June 16, 2016 FCC ID : 2AEFK-DL8791

Worst Case Position

Horizontal: X-axis / Below 1GHz: Vertical: X-axis Above 1 GHz: Horizontal: Z-axis / Vertical: Y-axis Bandedge: Horizontal: Y-axis / Vertical: Z-axis






Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124