
Report No.: 15031369HKG-001

## **Equipment Photographs**

Model: MP3441







Report No.: 15031369HKG-001

## **Equipment Photographs**

Model: MP3441






Report No.: 15031369HKG-001

# **Equipment Photographs**

Model: MP3441







Report No.: 15031369HKG-001

## **Equipment Photographs**

Model: MP3441







Report No.: 15031369HKG-001

### **Equipment Photographs**

Model: MP3441







Report No.: 15031369HKG-001

## **Equipment Photographs**

Model: MP3441







Report No.: 15031369HKG-001

# **Equipment Photographs**

Model: MP3441







Report No.: 15031369HKG-001

## **Equipment Photographs**

Model: MP3441

(Internal)





FCC ID: 2AEMAMP3441