


- 3. Component Side of Mother Board.
- 4. Solder Side of Mother Board.





- 5.Component Side of Chipset.6.Component Side of Antenna.



7.Inner 8.Inner





Report No: 1508006R-01 Tel:886-2-2603-5321 Fax:886-2-2603-5325

