

# **Appendix A. Test Photos**

Report No.: FR572330AL

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






Report No. : FR572330AL

### 1 Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.

: A2 of A6

Report Version

: Rev. 01





Report No.: FR572330AL



**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973







Report No.: FR572330AL

## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973


Page No. : A4 of A6 Report Version : Rev. 01




FCC Test Report

Report No.: FR572330AL

### For radiated emissions 30MHz~1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6 Report Version : Rev. 01




FCC Test Report

Report No.: FR572330AL

### For radiated emissions above 1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6

Report Version :

: Rev. 01