

153662_1.JPG: SEAANGEL SA15 AIS FLARE with 2J0936, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 11 of 15





153662_3.JPG: SEAANGEL SA15 AIS FLARE with 2J0936, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 12 of 15






153662_2.JPG: SEAANGEL SA15 AIS FLARE with IN2011, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 13 of 15





153662_4.JPG: SEAANGEL SA15 AIS FLARE with IN2011, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 14 of 15





153662_5.JPG: SEAANGEL SA15 AIS FLARE, test set-up temperature chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 15 of 15