# Appendix C. Setup Photographs

#### <Conducted Emission>

#### Mode 1




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C1 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL MA Version 1.3


Report No.: FR630205C

## X Plane For WLAN 802.11b/802.11g Chain Port 1/802.11n HT40

LF



HF




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C2 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL MA Version 1.3


Report No. : FR630205C

### X Plane For WLAN 802.11g Chain Port 2/802.11n HT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX829 Page Number : C3 of C3
Report Issued Date : May 03, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL MA Version 1.3

Report No. : FR630205C