
Appendix A. Setup Photographs

<Conducted Emission> Mode 5






Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : A1 of A4
Report Issued Date : Apr. 04, 2018
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No.: FC820819



Mode 7





Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : A2 of A4
Report Issued Date : Apr. 04, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 4

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : A3 of A4
Report Issued Date : Apr. 04, 2018
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No. : FC820819

Test Report No. : FC820819

Mode 6

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : A4 of A4
Report Issued Date : Apr. 04, 2018
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3