
## Appendix C. Setup Photographs


## <Radiated Emission>

Part 22H (Y plane)

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6H Page Number : C1 of C3
Report Issued Date : May 23, 2018
Report Version : Rev. 01

Report No. : FG820819-01A

Report Template No.: BU5-FG22/24/27 Version 2.0


Report No. : FG820819-01A

## Part 24E (Z plane)

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6H Page Number : C2 of C3
Report Issued Date : May 23, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 2.0


Report No. : FG820819-01A

## Part 27L (Y plane)

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6H Page Number : C3 of C3
Report Issued Date : May 23, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 2.0