
Appendix C. Setup Photographs


<Radiated Emission>

Part 22H

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XME1A Page Number : C1 of C3
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 2.0


Report No.: FG842002A

Part 24E/27L

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XME1A Page Number : C2 of C3
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 2.0


Report No. : FG842002A

Part 22H for CDMA

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-XME1A Page Number : C3 of C3
Report Issued Date : Jun. 11, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 2.0

Report No. : FG842002A