

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138 Page Number : D1 of D4
Report Issued Date : Feb. 13, 2017
Report Version : Rev. 01

Report No.: FR6D1401C

Report Template No.: BU5-FR15CWL Version 1.3




Report No.: FR6D1401C

<Radiated Emission>

Z Plane for 802.11b

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138

Page Number : D2 of D4 Report Issued Date : Feb. 13, 2017 Report Version : Rev. 01


Report Template No.: BU5-FR15CWL Version 1.3



Report No.: FR6D1401C

X Plane for 802.11g

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138

Page Number : D3 of D4 Report Issued Date : Feb. 13, 2017 Report Version : Rev. 01


Report Template No.: BU5-FR15CWL Version 1.3




Report No.: FR6D1401C

Y Plane for 802.11n HT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RSG138 Page Number : D4 of D4
Report Issued Date : Feb. 13, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.3